


Appendix 3 – Site Photographs



Site Photo 1: Toon River upstream of Toon Bridge



Site Photo 2: Dominant Toon River channel within Gearagh woodland



Site Photo 3: Dry anastomosed channel (note trapezoidal cross-section)



Site Photo 4: Debris dams within Gearagh woodland



Site Photo 5: Steep (close to vertical) banks along dominant Toon channel



Site Photo 6: Silty hollow arising following tree fall